

State of Connecticut

## ACCIDENT INFORMATION SUMMARY

CFS #.: 2400224949 Date: 06/10/2024 Department of Emergency Services and

Time: 23:18

State Police Troop: TROOP H

Primary Officer: DEAN, MICHAEL J

Location: Interstate 91 Northbound Windsor Intersection: Exit 38

## **Involved Vehicles**

Vehicle #:


Owner: Professional Partners International L Address: 30 Gregory Hill Dr Glastonbury Ct

Public Protection / Division of State Police

State: CT Model: RAM 3500 Plate: L27556 Make: Dodge Year: 1999 Vin: 3B6MF3669XM531478 Insurance Co.: **GEICO Indemnity Company** Policy #: 4501755047

Vehicle Towed: Yes Towed To: Mike's Auto

Damaged Area: Sector 7 (South by SouthWest) in the 12-point Clock Diagram Not Applicable Not Applicable



Vehicle Damage Diagram


Vehicle #: 2

Owner: Hill, Ronald Clayton Address: 25 Timothy Rd East Hartford Ct

Plate: 2ZYT97 Model: SANTE State: MA Make: HYUN Year: 2007 Vin: 5NMSH73E57H033975 Insurance Co.: **GEICO** Policy #: 6160228620

Vehicle Towed: No Towed To: N/A

Damaged Area: Sector 12 (North) in the 12-point Clock Diagram Not Applicable Not Applicable



Vehicle Damage Diagram


Vehicle #:

Owner: Schlagel, Jonathan Scott Address: 62 Hartford Ave Enfield Ct

Make: Triumph Year: 2000 Plate: 00NLBN State: CT Model: Sprint RS Vin: SMT605FM0YJ102990 Insurance Co.: **GEICO Indemnity Company** Policy #: 6031239988

Vehicle Towed: Yes Towed To: Mike's Auto

Damaged Area: Sector 12 (North) in the 12-point Clock Diagram Not Applicable Not Applicable



Vehicle Damage Diagram

## **Involved Persons**

Vehicle #: 1 Name: Ajdinoski, Minur M **D.O.B.**: 07/28/1978 **OP State & No.:** CT 197241502 Sex:

Address: 238 South Elm St Windsor Locks Ct

Status: Driver Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal veh

Protection System: Shoulder and Lap Belt Used Airbag Status: Not Deployed

Injuries: No Apparent Injury

Transported: No Transported By: N/A Hospital: N/A

Vehicle #: 2 Name: Hill, Ronald Clayton D.O.B.: 03/18/1997 OP State & No.: CT 039127008

Address: 25 Timothy Rd East Hartford Ct

Status: Driver Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal veh

Protection System: Shoulder and Lap Belt Used Not Deployed Airbag Status:

Injuries: Suspected Minor Injury

Transported: No Transported By: Windsor FMS Hospital:

Vehicle #: 3 Name: Schlagel, Jonathan Scott Sex: M D.O.B.: 07/10/1990 OP State & No.: CT 198315918

Address: 62 Hartford Ave Enfield Ct

Status: Driver Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal vel

Protection System: Not Applicable Airbag Status: Not Applicable

Injuries: Fatal Injury

Windsor EMS Hospital: Transported: No Transported By:

Vehicle 1 was traveling on Interstate 91 Northbound, south of exit 38, in the right lane of three. Vehicle 3 was traveling directly behind Vehicle 1. For an unknown reason, Vehicle 3 collided with the rear of Vehicle 1 and Operator 3 separated from Vehicle 3. Vehicle 2, which had been driving behind

> DATE SIGNED SUPERVISOR SIGNATURE AND BADGE NO. /SGT KEVIN R LITTAU/ 0292 06/11/2024



State of Connecticut

## ACCIDENT INFORMATION SUMMARY

Department of Emergency Services and Public Protection / Division of State Police

Date: 06/10/2024

CFS #.: 2400224949

Time: 23:18

State Police Troop: TROOP H

Primary Officer: DEAN, MICHAEL J

Location: Interstate 91 Northbound Windsor Intersection: Exit 38

Vehicle 1 and Vehicle 3, then collided with Operator 3 after Operator 3 separated from Vehicle 3. Vehicle 1 came to a controlled final rest in the right shoulder of Interstate 91 Northbound. Vehicle 2 came to a controlled final rest in the right shoulder of Interstate 91 Northbound. Vehicle 3 came to an uncontrolled final rest in the swale separating the HOV lane and the travel lanes of Interstate 91 Northbound. Operator 1 reported he was not injured and declined medical treatment at the scene. Operator 2 suffered suspected minor injuries and was treated at the scene by EMS. Operator 3 suffered injuries not compatible with life, and was pronounced deceased at the scene. Vehicle 2 was driven from the scene. Vehicle 1 and Vehicle 3 were towed from the scene due to disabling damage. This case remains under investigation. Any witness to the collision is asked to contact TPR Dean # 416, at Troop H, at 860-534-1098 or through email at michael.dean@ct.gov. Furthermore, if you have a vehicle equipped with a dashcam, and you were driving through the area at the time of the collision, you are also asked to contact TPR Dean.

SUPERVISOR SIGNATURE AND BADGE NO.

DATE SIGNED 06/11/2024